

---

**CERTIFICATE OF TANK SCAN**

APRIL 28, 2022

PRESENTED TO: KEN JOHNSTON

**4526 NEVILLE ST. BURNABY, BC**

The following represents our findings;

Tanktech Environmental Services Ltd (Tanktech) hereby certifies that the outer premises of the above noted property has been systematically scanned for an underground storage tank (UST) by means of a ferromagnetic detector.

The property was also visually checked for signs of a vent line, fuel lines and/or a filler pipe, none of which were observed.

Areas beneath the addition and the concrete in the backyard are inconclusive due to metal reinforcing, lack of access and/or interference. Metallic signatures were detected underneath the paving stones. These spots were probed to a depth of approximately 4' but didn't connect with anything. This paving stone area is also inconclusive.

After a thorough investigation, Tanktech did not locate a UST in or on the above noted property.



Ian Groves, Principal

**DISCLAIMER**  
SUBJECT TO THE FOLLOWING CONDITIONS AND LIMITATIONS: THE INVESTIGATION DESCRIBED IN THIS CERTIFICATE HAS BEEN CONDUCTED IN A MANNER OF A HIGH LEVEL OF CARE AND SKILL. OUR EQUIPMENT IS ACCURATE UP TO FIVE FEET BENEATH GRADE. ANY AREAS UNDER PERMANENT STRUCTURES, ADDITIONS, GARAGES, DECKS, WALLS, METAL FENCING, DRIVEWAYS, PAVING STONES AND MOST PATIOS ARE INCONCLUSIVE BECAUSE OF METAL REINFORCING OR LACK OF ACCESS. **THIS CERTIFICATE DOES NOT CONSTITUTE A GUARANTEE.** THIS CERTIFICATE MAKES NO REPRESENTATION OF FACT OR OPINION OF ANY NATURE WHATSOEVER TO ANY PERSON OR ENTITY OTHER THAN THE ORGANIZATION, COMPANY OR INDIVIDUAL TO WHOM THIS CERTIFICATE IS ADDRESSED. THE LIABILITY OF THIS CERTIFICATE IS LIMITED TO THE AMOUNT OF FEES RELATED TO THIS WORK. ACCEPTANCE OF THIS CERTIFICATE CONFIRMS ACCEPTANCE OF THE TERMS SET FORTH IN THIS DISCLAIMER.